FS-WDL80-1S



Key features

- No installation needed; the vacuum pad hangs directly on the crane hook.
- Vacuum is generated and released by slackening or tensioning the chain; pick-up and release are handled by the vacuum control valve.
- No control buttons, no electricity or external power source, and unaffected by power outages or low voltage.
- No electrical wiring or air hoses; the unit works anywhere a crane or hoist is available.
- The load is released only when it has been set down and the chain is fully slack, eliminating operating errors.

Specifications

Product code	Max. load	Dimensions (mm)	Pad diameter (mm)	Number of pads	Power system	Control mode	Unit weight
FS-WDL80-1S	80 kg	Φ200 x 550	Φ200	1 pad	No power required	Automatic	5 kg

Contact us for consultation and a quotation

Vietnam factory: Workshop A1-1, VSIP Hai Phong, Nam Trieu Ward, Hai Phong City · +84 817 888 198
Taiwan factory: Zhongli District, Taoyuan City · +886 3-451-8806
Email: sales@fullsharp.com.vn · **Website:** www.fullsharp.com

Specifications may vary with the ordered configuration. Please contact FullSharp for exact details.